

NOTE: SOME BOARDS ARE FITTED WITH
470 OHMS IN THIS POSITION. THIS IS WRONG!

